



Atellio family: NCP105

Firmware and AUDAC Touch™ update

We would like to bring you another update about the Atellio family. Please make sure you are always running the latest version of AUDAC Touch™. You can find the latest versions here: <https://audac.eu/eu/software/audac-touch>

Release: December 6th

- NCP firmware version: 1.0.4

New features

- Luna GPO triggering via Luna event handler and NCP105
- Event handler settings backup and restore via file browser
- NCP105 supports custom (single) commands via commander function in AUDAC Touch™ for, Atellio family*, Consenso family* & third-party equipment. No visual feedback yet for custom commands via the Commander function.

Known limitations for the latest version (December 6th)

NCP105 series - V1.0.4

- Will initially only work with the LUNA & the NWP series.
- The devices to control should have a static IP address.

Release: October 31st

- NCP105 firmware version: 1.0.2

New features

- Firmware updates of NCP105 and NWP Series via AUDAC Touch™ on the same network.
- NCP105 button auto-calibration
- NCP105 bug fixes
 - Improved stability for simultaneous use of buttons

Known limitations for the latest version (October 31st)

NCP105 series - V1.0.2

- Will initially only work with the LUNA & the NWP series.

- The devices to control should have a static IP address.

Release: September 13th

- NCP105 firmware version: 1.0.1
- Touch version: 2.11.1 Download it here:
<https://audac.eu/eu/software/audac-touch>

New features

- VU indication for all the Atellio family products.
- Increased NCP105 rotary volume control steps from 1dB to 3dB. No NCP firmware update needed, only reprogramming rotary via Audac Touch.

Release: August 31st

The initial batch of devices to be delivered will have all the latest firmware.

- NCP105 firmware version: 1.0.1
- Touch version: 2.11.0 Download it here:
<https://audac.eu/eu/software/audac-touch>

New features

- NCP105 configuration support in AUDAC Touch™.
- NCP105 rotary configuration with combined volume and mute (Configure rotary button to volume),
- Device connection indication on settings screens in Touch.
- IP address configuration without Touch restart.
- Connection status of the Atellio family products.